



1. CONNECT PROBE TO DOWNLOAD CABLE (A)
2. TURN ON INSTRUMENT POWER, ALLOW START-UP SEQUENCE TO COMPLETE.
3. REMOVE DOWNLOAD CABLE AND INSTALL PROBE AT REMOTE LOCATION WITH CABLE (B)

TOLERANCES EXCEPT AS NOTED	REVISIONS			<b>NYAD, INC</b>		
	NO	DATE	BY			
DECIMAL	1	5/0/97		DRAWN BY	SCALE	MATERIAL
FRACTIONAL				MM	N/A	
ANGULAR				CHK,D	DATE	DRAWING NUMBER
				TRACED	APP'D	